

ECOLOGY AND ENVIRONMENT, INC.
FIELD INVESTIGATION TEAM
ON-SITE SAFETY MEETING

US EPA RECORDS CENTER REGION 5



472875

Project Corning Glass - Zirconia Prod.

Date 6-16-87 Time 9:00 AM Job No. FOH0184/SI

Address 31501 Salton Rd. Salton Ctl.

Specific Location 31501 Salton Rd (Cuyahoga Co.)

Type of Work Onsite Inspection, Interview. No samples collected.

SAFETY TOPICS PRESENTED

Protective Clothing/Equipment Level D

Chemical Hazards HF & HCl Acids, Heavy Metals

Physical Hazards Open Lagoon, & open drying beds.

Emergency Procedures None specifically except Hospital Route. Buddy System, Action Levels.

Hospital/Clinic Community Hosp. of Bedford Phone 216 439 2000

Special Equipment NONE

Other NA

ECOLOGY AND ENVIRONMENT, INC.
FIELD INVESTIGATION TEAM
ON-SITE SAFETY MEETING

ATTENDEES

Name (Printed)

Signature

Pat Petrella

Pat Petrella

Dave Heidlauf

D. Heidlauf

Dirk Kaiser

Dirk Kaiser

Meeting Conducted By:

Pat Petrella

Pat Petrella

Site Safety Officer:

Pat Petrella

Pat Petrella

Team Leader:

Pat Petrella

Pat Petrella

30 minutes

ON-SITE SAFETY LOG

ECOLOGY AND ENVIRONMENT, INC.
CHICAGO

A. ON-SITE MONITORING

	EQUIPMENT USED	BACKGROUND READING IN BREATHING ZONE	CALIBRATED AT span 3.0	ON-SITE READING IN BREATHING ZONE
1.	OVA	16.1	1.0	16
2.	Rad. Mini	13 beats/min	NA.	13 ^{NO} ALARM
3.				
4.				
5.				

B. PROTECTIVE CLOTHING WORN:

Level D

C. SITE NAME: Corning Glass Works - Zircos Prod. PROJECT NUMBER: FOHO 18451

DATE: 6-16-87

WEATHER CONDITIONS: 86°F, clear

NAMES OF ATTENDEES AT SITE: D. KAISER, D. Heidlauf.

D. COMMENTS ON MONITORING OR PROTECTIVE CLOTHING

None

TEAM LEADER:

NAME
Pat Petrella

SITE SAFETY OFFICER:

Pat Petrella

SIGNATURE

Pat Petrella
Pat Petrella